



STATE OF ILLINOIS ENVIRONMENTAL PROTECTION AGENCY
SCRAP TIRE STORAGE SITE INSPECTION REPORT

RECEIVED

JUN 13 1989

IEPA/DLPC

COUNTY ST. CLAIR SITE CODE 1 6 3 1 2 1 0 0 1 7

TIME: from 2:00 to 2:30 PHOTOS TAKEN: YES ☒ NO ☐

FACILITY SAUGET/MIDWEST RUBBER INSPECTION DATE 6/29/89

ADDRESS 3101 MISSISSIPPI AVE APPROX. # TIRES 150,000

SAUGET 62201 REGION 6 INSPECTOR Steve Negatti

SITE OWNER MIDWEST RUBBER SITE OPERATOR _____

ADDRESS SAUGET ADDRESS _____

PHONE # (618) 331-6400 PHONE # _____

INTERVIEWED GEORGE MARTYCHENKO SAMPLES COLLECTED: YES ☐ NO ☒

849.103 REPORTING REQUIREMENTS:

- (a) Has a report been submitted to the Agency? Note: report due by 7/1/89 (if > 50 tires are on site) or within 45 days of an accumulation of 50 tires.

YES ☒ NO _____ N/A _____

- (e) Has a written compliance plan been developed, and are records available to demonstrate implementation of the compliance plan?

YES ☒ NO _____ N/A _____

849.104 MANAGEMENT STANDARDS:

NOTE: Management standards apply between April 1, and November 1, to persons accumulating more than 50 scrap tires. However, scrap tires accumulated solely as a result of personal, agricultural, horticultural, or livestock raising activities are not subject to 849.104.

- (b) Are the scrap tires drained of water on the day of generation or receipt and kept dry by being:

- A) Placed within a closed container or structure; or
B) Covered by material impermeable to water; or
C) Drained within 24 hours after each rain.

YES _____ NO ☒

APPARENT
VIOLATION


00100

STATE OF ILLINOIS
ENVIRONMENTAL PROTECTION AGENCY

SITE SKETCH

Date of Inspection: 29-JUNE-1989 Inspector: STEVE NODRITT
Site Code: 1631210017 County: ST. CLAIR
Site Name: SAUGET / MIDWEST RUBBER Time: 200-230 PM

4
N



RECEIVED
JUL 13 1989
IEPA/DLPC

9323001297

001060